




ASSEMBLY AND OPERATING INSTRUCTIONS FOR FUN3245



STEP 1:
CONNECT THE 4 LEG POLES
TO THE BASE FRAME AS
SHOWN BELOW.



STEP 2:
NEXT SLIDE THE SHOES DOWN
OVER THE POLES, FOLLOWED
BY THE SUIT. THEN CONNECT
THE TORSO FRAME OVER THE
LEG POLES. THEN ATTACH THE
SHOULDER FRAME TO THE TOP
OF THE TORSO FRAME.




STEP 3:
PULL SUIT UP THE ASSEMBLED FRAME
AS SHOWN BELOW.



STEP 4:
NOW PUT ON THE COAT
OVER THE ASSEMBLY.



STEP 5:
TAKE THE LEFT ARM FRAME
AND SLIDE IT UP INTO THE
LEFT SLEEVE OF THE COAT.




THIS IS EASIER DONE BY MOVING THE
COAT TO EXPOSE THE ARMPIT AREA.
DO THE SAME STEPS TO CONNECT
THE RIGHT ARM FRAME TO THE
BODY THOUGH THE RIGHT SLEEVE

STEP 6:
CONNECT THE HANDS TO
THE METAL HOLDERS WHICH
ARE LOCATED IN THE WRIST
AREA OF THE ARM FRAMES.




STEP 7:
ASSEMBLE CANE BY CONNECTING 2 PIECES.
PLACE IN RIGHT HAND.




STEP 8: CONNECT THE HEAD
TO THE SHOULDER FRAME AS
SHOWN BELOW.



MAKE SURE NECK
PRONGS ARE FULLY
INSERTED INTO THE
METAL HOLDER.



STEP 9:
GO BEHIND THE ITEM. PULL THE
BACK OF THE COAT DOWNWARD
TO EXPOSE THE INSIDE CAVITY OF
THE TORSO. LOCATE THE WIRE
DANGLING FROM THE NECK AND
CONNECT IT TO THE WIRE
DANGLING FROM THE TORSO
FRAME.



STEP 10: WHILE STILL BEHIND
THE ITEM, PLUG-IN THE FOOTPAD
TO THE CONTROL BOX (TRY ME JACK)
AND RUN IT DOWN ONE OF THE PANT
LEGS AND OUT ONTO THE FLOOR
FOR USE.



CONTROL BOX GUIDE:



NOTE: SLIDING THE POWER SWITCH TO THE "ON" POSITION
ACTIVATES THE SENSOR FUNCTION.
SLIDING IT TO THE "OFF" "TRY ME" POSITION DEACTIVATES THE
SENSOR FUNCTION AND ACTIVATES THE
TRY ME BUTTON FUNCTION.



STEP 11: AFTER
ALL WIRE
CONNECTIONS
HAVE BEEN MADE
PULL HIS COAT BACK
UP AND OVER HIS
SHOULDERS.

STEP 12 : CONNECT THE VELCRO PATCHES
ON HIS OUTFIT LOCATED BEHIND HIS NECK
AND ON HIS VEST FRONT.

ITEM FEATURES:
-MOTION
-SOUND
-LIGHT UP EYES



PLUG THE ITEM
INTO A POWER
SOURCE AND LET
THE HAUNTING
BEGIN!